

THIS PAGE IS UNCLASSIFIED

REF ID: A66884

APPENDIX "E"

CONSOLIDATION OF BATTLE DAWGS.
MEDICAL-LOGGING OPERATION.



Serial	Altitude	Engine	Wing	Wing	Wing	Wing	Wing	Wing	Wing
43-16026	434th 71st		Y						Nine (9) light flak holes in fuselage by navigators seat. One (1) hole in each wing. 2nd
42-93795	71st	X							One (1) 30 cal. hole in cargo door. 1st
43-15220	72nd			X					Small arms hole in left elevator. Elevator needs to be changed. 2nd
42-100506	72nd	X							Small arms hole in left wing 1st
42-100505	72nd	X							Small arms hole in left horizontal stabilizer 1st
42-24047	73rd			X					(1) 3 in. hole in left wing near nacelle. 2nd
42-24048	73rd	X							(1) small hole bottom of fuselage near door. 1st
43-15627	74th	X							Small arms hole in fuselage. 1st
42-24062	74th	X							Small arms hole in left wing. 1st
									24 DECEMBER 1944
42-24062	74th			X					Small arms hole in left wing and nose section. 2nd
									26 DECEMBER 1944
42-24050	73rd								Not returned. Forced down in France. Damage unknown
43-15666	73rd				X				Rudder trim tab blown off by flak. One foot flak hole in vertical stabilizer. One foot flak hole in fuselage near empennage section. Numerous holes in right elevator. 3rd
43-15349	71st	X							Holes caused by small arms fire. 1st
42-4040	73rd				X				Rudder damaged beyond repair. Rudder hinge damaged. Flak hole in horizontal stabilizer. Flak holes in astro dome. 3rd



PAGE ONE

Serial	Altitude	Engine	Wing	Wing	Wing	Wing	Wing	Wing	Wing
42-93040	73rd	X							Small arms hole in left wing 1st.
42-108992	72nd				X				Hydraulic system shot out. 3rd.
42-100500	72nd	X							Four bullet holes in wing and one in tail section 1st.
43-16031	72nd			X					Bullet hole in battery box. 1st.
42-24053	74th				X				Rudder and elevator trim tab cables shot away. Rudder and elevator cables must be replaced. Damaged by flak burst in empennage. 3rd.
43-15027	74th	X							Small arms damage. 1st.
42-24024	71st	X							Small arms damage. 1st.
42-24022	71st	X							Small arms damage. 1st.
43-15011	71st	X							Small arms damage. 1st.
43-15350	74th	X							Small arms damage. 1st.
42-24060	74th	X							Small arms damage. 1st.



"A"	"B"	"C"	"D"	"E"	"F"	"G"	"H"
42-24074	76th	X					Small Cal. bullet hole right horizontal stabilizer. 2nd
43-15222	76th	X					Small Cal. (30) in left elevator trim tab 1st
42-24121	77th	X					One 30 caliber hole in left wing 2nd
43-15192	77th		X				One 30 caliber hole in belly. Small hole in skin, two fuel lines hit. 2nd
42-92844	77th	X					One 30 caliber hole in left wing which missed two spars. One 30 caliber hole through antenna mast, 1 1/2 inch hole in belly and 3/4 inch hole in cabin floor, one 30 caliber hole in left elevator. 2nd
42-24132	77th	X					One 30 caliber hole in left wing. 2nd
42-100510	77th	X					One 30 caliber hole in center of left wing. Two 30 caliber holes in belly. One fiak hole in nose. 2nd
43-15297	77th	X					One thirty caliber hole in tail wheel tire. One hole through vertical stabilizer, one hole through horizontal stabilizer. 2nd
42-24095	77th	X					Jump panel frame damaged through operational action. 2nd
42-68727	76th		X				Small hole in Left Wing A/C at A-41 2nd
43-48870	76th						Emergency Landing at A-83 Damage unreported.
43-48944	76th						Emergency Landing at A-83 Damage unreported.
43-48497	76th						Missing-No proof that it is a complete loss to enemy action.
43-48926	76th						Missing-No proof that it is a complete loss to enemy action.



435th TC Group

S E C R E T

"A"	"B"	"C"	"D"	"E"	"F"	"G"	"H"
43-48936	76th						Missing in action - Shot down at B.
43-30731	76th						Missing in action - Shot down at W. 24 DECEMBER 1944
43-43547	75th	X					Two (2) 30 Cal. bullet holes, wing and fuselage. 2nd
43-48711	76th		X				Four fiak holes in left wing and aileron, one fiak hole in fuselage. 2nd
42-100510	77th	X					One thirty caliber hole in left aileron. 2nd
42-92094	77th	X					One fiak hole in right top fuselage, 2 inches large. One fiak hole in right wing fillet, two fiak holes in fuselage. 2nd
42-24072	76th	X					Small arms damage. 2nd
43-15618	78th	X					Small arms damage to rudder. 2nd
42-92666	78th	X					Small arms damage. 2nd
							26 DECEMBER 1944
43-48472	75th	X					1 30 Cal. hole in left wing. 2nd
43-48716	75th		X				8 30 Cal. holes in left wing, 1 fiak hole in left aileron. 2nd
43-48718	75th						Lost to enemy action in enemy territory.
43-48389	76th	X					Small arms damage. 2nd
43-48803	76th	X					Small arms damage. 1st
43-48499	76th	X					Small arms damage. 1st
43-48725	76th		X				Elevator trim tab cable cut by 30 cal. bullet 2nd
43-48901	76th	X					Small arms damage. 1st



"A"	"B"	"C"	"D"	"E"	"F"	"G"	"H"
43-48960	76th	X					Flak hole in mid section of left wing, 30 cal. 2nd bullet hole in trailing edge of right wing.
43-48940	76th	X					Small arms damage. 2nd
42-24192	77th				X		One thirty cal. hole in right wing, two stringers damaged. 3rd
42-24132	77th	X					One thirty cal. hole in right wing, one thirty cal. hole thru instrument panel. 2nd
42-24121	77th	X					Small arms damage. 2nd
42-92644	77th	X					One thirty cal. hole in right side of belly coming out top of right center section damaging spar. 2nd
42-24042	77th				X		Small arms damage, to hydraulic system, wing spars and fuselage. 3rd
42-24095	77th	X					One 30 cal. hole thru horizontal stabilizer. 2nd
42-100510	77th	X					One 30 cal. hole thru belly. 2nd
42-23928	77th				X		One 30 cal. hole entering fairing of wing bolts passing through to leading edge. Damage internally undetermined. 3rd
42-68792	77th	X					One explosive bullet thru vertical stabilizer. 2nd
42-68752	77th						Emergency landing in France due to wounded. Damage unknown.
42-24026	78th				X		Oil tank shot out - A/C located at A-83. 1st
42-24072	78th			X			Small cal. damage in right out board wing stringers. 2nd
42-24074	78th			X			Small cal. hole in right wing. 2nd



27 DECEMBER 1944

"A"	"B"	"C"	"D"	"E"	"F"	"G"	"H"
42-24134	76th				X		Right engine shot out. 1st
42-100658	78th				X		Emergency landing - Hydraulic line shot out Plane hit pile of rock and asphalt causing right landing gear to buckle and damaging right wing, engine and propeller and center section. 3rd
42-100669	78th			X			Small arms damage. 2nd
43-15209	78th			X			Small arms damage. 2nd
43-15261	78th	X					Small arms damage. 2nd
42-68736	78th	X					Center of fuselage has 30 cal. hole thru it. 2nd
42-93812	78th	X					Small cal. hole in right horizontal stabilizer 2nd
43-48961	76th	X					Small flak hole in nose section of fuselage. 2nd
42-100897	78th				X		Aircraft at A-39, damage unknown.
42-93812	78th				X		Aircraft at A-39, damage unknown.

"A"	"B"	"C"	"D"	"E"	"F"	"G"	"H"
42-15558	79th	X				Small bullet hole in left wing.	2nd
42-100558	81st	X				Bullet hole leading edge left wing.	2nd
42-100552	81st		X			Bullet hole leading edge left wing and right magneto & left engine inoperative.	2nd
42-100673	82nd	X				Small arms damage.	1st
42-92092	82nd	X				Small arms damage.	1st
42-93279	82nd		X			Flat tire caused by small arms fire.	1st

26 DECEMBER 1944

42-100670	79th	X				Small arms hole through right nacelle damaging main line fuel strainer.	2nd
43-15640	79th			X		Bullet pierced right on line through #10 cylinder barrel, piston and articulating rod.	2nd
42-93607	79th			X		2 Bullet holes in center wing cutting aileron tab control cable.	2nd
42-100525	79th	X				Two small arms holes in tail cone and elevator	1st
42-100526	79th	X				Two small arms holes through fuselage	2nd
43-15008	79th	X				One small hole in right wing and one hole in right cowl flap.	2nd
43-15109	80th	X				Small arms damage.	1st
43-48332	89th			X		One 30 cal. hole in right auxiliary gas tank Four 30 cal. holes in right wing, inboard sec. of root. Bad dent on landing gear brake strut	4th



42-100542	80th	X				Small arms damage.	1st
42-100539	80th			X		One 30 cal. hole in left main gas tank, one 30 cal. hole thru left engine mount support bracket.	4th
42-100543	80th	X				Small arms damage.	1st
42-100548	81st			X		Bullet puncture left main tank.	3rd
42-100547	81st	X				Small arms damage.	2nd
42-100533	81st	X				Several small flat holes in bottom fuselage two bullet holes in front fuselage.	2nd
42-15501	81st	X				Small arms damage.	2nd
42-100552	81st	X				Windshield de-icer tank damaged.	2nd
42-100557	81st	X				Command TV antenna shot off. Hole in right elevator.	2nd
42-93072	82nd			X		Flat tire on left wheel. Small arms damage to both wings.	1st
42-24069	82nd	X				Small arms damage to tail section.	1st
42-93275	82nd	X				Small arms damage.	1st
42-100673	82nd	X				Small arms damage.	1st
42-100565	82nd		X			One hole in left main tank.	1st
43-15291	82nd	X				Small arms damage in rear fuselage, radio set set out.	1st
43-30729	82nd	X				Small arms damage.	1st

Serial	Group	Date	Location	Description	Priority
42-100509	82nd			Hole in No. 10 cylinder on left engine. Hole in fuselage forward of center section. Hole in tail section. Hole in left wing.	3rd
42-100512	82nd			Hole in horizontal stabilizer.	1st
42-100503	82nd			Two holes in right wing. Two holes in right elevator. One hole in side of fuselage.	1st
42-100506	82nd			One hole in right wing.	1st



437th T.F. Group

REPAIRS

Serial	Group	Date	Location	Description	Priority
2) 10 OCTOBER 1944					
42-100504	84th		X	Hole in fuselage below cargo door.	1st
42-15493	84th		X	Two 30 cal. holes in right wing.	1st
42-24303	84th		X	Hole in nose section (30 cal.).	1st
42-100609	85th		X	Flak hole in left elevator	1st
42-16033	85th		X	Small arms damage.	1st
42-100637	85th		X	Small arms damage.	1st
42-15330	85th		X	Flak hole in frame of cargo door.	1st
24 OCTOBER 1944					
42-15107	84th			Small arms damage.	1st
42-100647	85th		X	Small arms damage.	1st
42-100660	86th		X	Right wing and right aileron damaged.	2nd
20 NOVEMBER 1944					
42-100572	83rd		X	One hole thru left auxiliary fuel tank.	2nd
42-100772	83rd		X	One hole in vertical stabilizer.	2nd
42-48225	83rd		X	Small arms damage.	1st
42-100590	84th		X	Small arms damage to right wing.	1st
42-100591	84th		X	Small arms damage to left wing.	1st
42-15107	84th		X	Two flak holes in left wing.	3rd



437th T.O. Group

S E E R E E

SN	GR	CD	DT	RE	RE	RE	RE	RE
42-10037	84th	X					Small arms damage in left elevator.	1st
42-10038	84th			X			Bullet hole thru pilots window into hydraulic reservoir.	1st
42-10038	85th			X			Bullet hole in fuselage at battery plug. 1st antenna out.	1st
42-10037	85th			X			Small arms damage to fuselage. 2nd antenna wiring out.	1st
43-10254	85th			X			Bullet hole in left wing, stringer out. Two bullet holes in empennage.	3rd
43-10514	85th			X			Bullet hole thru right nose. Landing gear hydraulic line punctured.	1st
43-48251	85th			X			Abdualt altimeter antenna shot off. 1st antenna bent. Parachute torn off.	3rd
42-100657	86th	X					Small arms damage to fuselage.	1st
42-100982	86th	X					Small arms damage to fuselage.	1st
27 DECEMBER 1944								
43-10315	84th	X					Small arms damage to left wing.	1st
42-10049	85th	X					Small arms damage to left wing.	1st
42-100632	85th			X			Rudder cable severed (airplane grounded far shore).	1st
42-92096	86th	X					Small arms damage to fuselage.	1st
43-15313	86th	X					Small arms damage to fuselage.	1st



438th T.O. Group

S E E R E E

23 DECEMBER 1944

SN	GR	CD	DT	RE	RE	RE	RE	RE
42-24387	87th						Emergency landing in UK, reason unknown.	
42-92087	88th						Lost in action.	
42-100704	89th	X					One parachute damaged.	2nd
42-100705	89th	X					Small arms damage, right wing tip, right aileron, right horizontal stabilizer.	2nd
43-10512	89th	X					Small arms damage to fuselage and right wing.	2nd
42-93077	89th	X					Hole in left wing and left elevator.	2nd
42-92899	90th	X					Small arms hole in left aileron.	1st
42-100810	90th	X					Small arms hole in right wing.	1st
42-93709	90th			X			Small arms hole in right main gas tank.	1st
42-100811	90th			X			Small arms hole in center section of wing. Small arms hole in wiring of right nacelle.	1st
24 DECEMBER 1944								
42-24387	87th	X					Small arms bullet damaged windshield de-icer tank.	2nd
42-24182	87th			X			Right aileron, right wing tip and de-icer boot damaged by heavy cal. shell.	3rd
42-100734	88th			X			Large flak hole in trailing edge of center wing section near fuselage on right side. Also numerous small flak holes and small arms fire in fuselage.	4th
26 DECEMBER 1944								
42-88615	87th	X					Small arms damage to left wing.	1st



SN	UNIT	TYPE	DATE	DESCRIPTION	STATUS
42-100743	87th		X	2 small bullet holes in tailcon and one in left horizontal stabilizer.	1st
42-92871	87th		X	Small arms damage.	1st
42-100739	87th	X		Small arms damage to right wing.	1st
42-100762	88th	X		Small bullet hole in left wing.	1st
42-15670	89th	X		One paratroop damaged by small arms fire.	1st
42-24196	89th	X		Small arms damage to left wing.	1st
42-100768	89th	X		Right lower brake line and right main tire shot out by small arms fire.	1st
42-15330	89th	X		Small arms fire thru rear of ship.	1st
42-92897	89th	X		Tail wheel tire punctured by small arms fire.	1st
42-100813	90th	X		Small arms hole in trailing edge of left center wing.	1st
42-108983	90th	X		Elevator trim tab cable severed.	1st

